

Montevina Intel® Management Engine

BIOS Extension 4.0.1.0007

<September 18, 2007>

<September 18, 2007>

DISCLAIMER: Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty relating to sale and/or use of Intel products, including liability or warranties relating to fitness for a particular purpose, merchantability or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, lifesaving, or life-sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

* Other names and brands may be claimed as the property of others.

Copyright © Intel Corporation 2007

This document contains information on products in the design phase of development. The information herein is subject to change without notice. Do not finalize a design with this information.

Revision History

Date	Revision	Draft/Changes
August 29 st , 2007	4.0.1.0005	Intel® Management Engine BIOS Extension
September 25 th , 2007	4.0.1.0006	Intel® Management Engine BIOS Extension
September 28 th , 2007	4.0.1.0007	Intel® Management Engine BIOS Extension

New Features

New Features (or changes) in < Build name and number >

Reference No.	Description
New Features in Intel® Management Engine BIOS Extension 4.0.1.0005	
N/A	PKI Provisioning support is included
New Features in Intel® Management Engine BIOS Extension 4.0.1.0006	
N/A	Added new USB provisioning fields in support of USB v2.1 file format.
N/A	Added descriptive error code messages on ME Firmware message failures.

Known Issues

Known Issues in < Build name and number>	
Reference No.	Description
Known Issues in Intel® Management Engine BIOS Extension 4.0.1.0005	
2517513	The MEBx allows the user to change the password only once per session

Resolved Issues

Resolved Issues in < Build name and number>	
Reference No.	Description
Issues Resolved in Intel® Management Engine BIOS Extension 4.0.1.0005	
N/A	None. Initial Release.
Issues Resolved in Intel® Management Engine BIOS Extension 4.0.1.0006	
2517177	Fixed SMBIOS table error in corner case scenario
2484551	Added new flow to update tables when performing USB provisioning
2485693	Error message is displayed when updating static IP on non-supported system
2516931	Fixed verify password flow on first MEBx entry
2517502	Added support for FOV locking variables
2515713	Added support for multiple password change attempts
2518723	Fixed multiple hash entry with USB provisioning
2518725	Fixed menu alignment issue when selecting a new power policy
Issues Resolved in Intel® Management Engine BIOS Extension 4.0.1.0007	
2519064	Fixed hash display when data contains double 00's
2518393	Display an error when a NULL Host Name is entered